Exova Warringtonfire Aus Pty Ltd Suite 2002a, Level 20 44 Market Street Sydney, New South Wales 2000 Australia T: +61 (0)2 8270 7600 F: +61 (0)2 9299 6076 W: www.exova.com

Postal Address: Suite 2002a, Level 20 44 Market Street Sydney, New South Wales 2000 Australia

Testing. Advising. Assuring.



Report Sponsor	Certificate Issue Date	Product Name
Am-boss Access Ladders Pty Ltd 11-13 Maida Ave, Sunshine North, VIC 3020	18/08/2014	Am-boss, 'Access Boss' pull dowr access ladder

Assessment Report Reference	Test Methods	Report Issue Date	Report Validity Date
BWA 22794-01	AS1530.4-2005	28/01/2009	31/01/2014
EWFA 31193800 (review of 22794-01)	AS1530.4-2005	18/08/2014	31/08/2019

Introduction

The element of construction described below was assessed by this laboratory on behalf of the report sponsor in accordance with the stated test standard and achieved the results stated below. Refer to the referenced assessment report(s) or Regulatory Information Report(s) for a complete description of the assessed construction.

## **Description of Assessed Product and Performance**

The assessed construction comprised an Amboss ceiling mounted access hatch and ladder assembly in a plasterboard ceiling if tested in accordance with AS 1530.4–2005. The assessment was reviewed and revalidated on 18/08/2014 to be valid to 31/08/2019.

Am-boss Hatch FRL	-/90/90	
Resistance to Incipient Spread (RISF)	90 minutes	

Refer to the referenced assessment report(s) or Regulatory Information Report(s) for a complete description of the assessed construction.

## Conditions/Validity

- THIS CERTIFICATE IS PROVIDED FOR GENERAL INFORMATION ONLY AND DOES NOT COMPLY WITH THE REGULATORY REQUIREMENTS FOR EVIDENCE OF COMPLIANCE.
- Reference should be made to the relevant test report or regulatory information report to determine the applicability of the test result to a proposed installation. Full details of the constructions and justification for the conclusions given, along with the validity statements, are given in the assessment reports.
- The results of these fire tests may be used to assess fire hazard, but it should be recognized that a single test method will not provide a full assessment of fire hazard under all conditions.

TESTING AUTHORITY	Exova Warringtonfire Aus Pty Ltd			
Address	Suite 2002a, Level 20, 44 Market Street, Sydney NSW 2000, Australia			
Phone / Fax	+61 (0)2 8270 7600 / +61 (0)2 9299 6076			
ABN	81 050 241 524			
Email / Home Page	www.exova.com			
Authorisation	Prepared By:	Reviewed By:		
	Micholson	Jula Amilla		
	D. Nicholson	K. G. Nicholls		

